Di-Log Test Equipment 28 Wheel Forge Way, Trafford Park, Manchester M171EH, UK tel: + 441618770322 fax + 441618771614 email: sales@dilog.co.uk website: www.diloa.co.uk

Maintenance

your meter unless you are qualified to do so and have the relevant calibration, performance test and service information. To avoid electrical shock or damage to the meter do not get water inside the case.

Periodically wipe the case with a damp cloth and mild

detergent. Do not use chemical solvent. Clean the input terminals with cotton bud, as dirt or moisture in the terminals can affect readings.

Outside the warranty period we offer a full repair and re-calibration service.

WARNING Do not attempt to repair or service

by the warranty

Damage due to dropping abuse or misuse is not covered

not been tampered with and returned to us unopened.

rectified by us free of charge, provided the instrument has

with invoice). Faults in manufacture and materials defect will be

controls. If in the course of normal daily use a fault occurs we will provide a 24 month warranty (only valid

24 Month Warranty Di-Log instruments are subject to stringent quality

to be stored for long periods.

S. Continuity lest

Resistance, Diode

DC/DC Ad

LUNCTION

VOOOF IIITAD .

bine roucu

Pouble Molded housing

V DC or V AC

Diode, Resistance or Continuity tests.

Autoranging with auto power off

and Overload protection on all ranges

· Built-in non-contact AC voltage detector

3-7/2 digit (4000 count) LCD display

SOOmA/500V Resettable Fused current inputs

· Kemove the battery from the meter if the meter is

trom the device under test before performing

Always discharge capacitors and remove power

I nese voltages are considered a shock hazard.

Voltages are greater than 25VAC rms or 35VDC.

· Use great care when making measurements it the

2600V DC/AC

OA\DU V008

Indui mumixeivi

acting Resettable Fuse

tset VOO2\AmOOS

Warranty & Maintenance

connecting the meter to the circuit. tuses and turn off power to the circuit before Betore measuring current check the meters

Non-contact AC voltage detector probe tip

Non-contact AC voltage indicator light

may give talse readings. indicator appears. If the battery is low the meter Keplace the battery as soon as the low battery

Meter Description

31/2 Digit (4000 count)

MODE button

Function switch

2.

3

4

5

6.

7

8

9.

10

may have leaked. A leaking battery will damage long period. Constantly check the battery as it Kemove the battery if the meter is in use for a I urn the meter power off when not in use,

service technician for calibration and repair. The meter may only be opened by a qualitied

Replace damaged leads with identical model or exposed metal. Check the leads for continuity.

inger guards. When using test leads keep tingers behind the (not supplied) these are available from Di-Log. Where applicable use GS38 approved leads

perween any terminal and ground. marked on the meter between the terminals or

etore making a measurement ensure the

measurement position and reduce the range pe measured is not known use the maximum range for your measurements. If the value to Dise the appropriate terminals, tunction and

field. The performance and safety of the use Do not use or store the meter in an environment

Disconnect circuit power and discharge all high

specification before using the meter. Check the test leads for damaged insulation or

Do not apply more than the rated voltage, as

. measurement. Do not turn the rotary switch whilst making a rotary switch is set to the appropriate range.

oprained. si buipeau Alactory reading is

may be compromised in such circumstances. gaseous, inflammable and strong magnetic of high temperature, humidity, tumes, vapour,

continuity, diodes, capacitance or current. voltage capacitors before testing resistance,

. De linpaired. manner specified, the protection provided may condition. If this meter is not used in the buitetado ates e ul tatam ant printerniem prie be tollowed tor operating the meter safely This manual contains intormation that must

refer to the instruction manual to avoid \overline{V} Warning! Warns of potential danger,

personal injury or damage to the meter.

electrical shock \$ Caution! Dangerous voltage. Danger of

IT asels, a life with IEC536, class IT Continuous double or reinforced

contormity with relevant EU directives. 3) Symbol of contormity, confirms

I-OIOIO NE brebness off in bounded L the Low Voltage Directive (/3/23/EEC) EN 50087-1 and EN 50082-1 as well as (89/336/EEC). Specifically standards The meter complies with EMC directives

with the safety regulations for electronic The meter has been designed in accordance

Voltages above 75V DC or 50V AC may measuring instruments, EM 61010-1, IEC 61010

connectors. If the case is damaged do not use gamage to the casing in particular around the Before using the meter check for physical constitute a serious shock hazard.

.າອາອຸເກ ອຸເກ

1882 8 100.00 (all 32, m) 2

H volts Multimeters C/DC RCD Voltage µF 16th Edition Edition Phase Rotation Clamp istance Continuity LOOD Portable • AC/DC

EN

61010-1

CAT III

600V

DL114



Voltage 16th Editio

Phase Rotation

operating manual







Specifications

Electrical Specifications

Function	Range	Accuracy
DC Voltage	200mV	± (0.5% rdg + 3d)
	2.000V, 20.00V, 200.0V, 600V	± (1.2% rdg + 3d)
AC Voltage 40-400Hz	2.000V, 20.00V	± (1.0% rdg + 8d)
	200.0V, 600V	± (2.3% rdg + 10d)
DC Current	200.0μΑ, 2000μΑ	± (2.0% rdg + 8d)
	20.00mA, 200.0mA	
AC Current	200.0μΑ, 2000μΑ	. (2 E% rdg . 10 d)
	20.00mA, 200.0mA	± (2.3% rug + 10d)
Resistance	200.0Ω	± (0.8% rdg + 5d)
	2.000kΩ , 20.00kΩ, 200.0kΩ	± (1.2% rdg + 5d)
	2.000ΜΩ	± (5.0% rdg + 5d)
	20.00ΜΩ	± (10.0% rdg + 5d)

Max input voltage	600V AC/DC	
Diode Test	Test current 1mA max., open circuit voltage of 1.5V typical	
Continuity Check	Audible signal if the resistance is <150 $\!\Omega$	
Display	2000 count 3 -1/2 digit LCD	
Over range indication	LCD displays "OL"	
Polarity	Minus (-) sign for negative polarity	
Low Battery Indication	"BAT" symbol indicates low battery condition	
Input Impedance	>7.5MΩ (VDC & VAC)	
AC Response	Average responding	
ACV Bandwidth	50Hz to 400Hz	
Auto Power Off	15 minutes (approximately)	
Fuse	mA, μA ranges; 0.2Α/500V fast acting Resettable Fuse	
Batteries	Two 1.5V AAA	
Operating Temperature	32°F to 104°F (0°C to 40°C)	
Storage Temperature	14°F to 122°F (-10°C to 50°C)	
Weight	145g	
Size	104x55x32.5mm	
Standard	IEC1010 CAT III 1000V Pollution degree II, CE Approved	

Operation

AC/DC VOLTAGE MEASUREMENTS

CAUTION: Do not measure AC/DC voltages if a motor on the circuit is being switched ON or OFF. Large voltage surges

- may occur that can damage the meter. 1. Set the function switch to the V position.
- Press the MODE button to indicate "DC" or
- "AC" on the display.
- Connect the black test probe tip to the negative side of the circuit.
 Connect the red test probe tip to the positive side of the circuit.
- 4. Read the voltage in the display

DC/AC CURRENT MEASUREMENTS

- Set the function switch to the µA/mA position.
 For current measurements up to 200mA
- 2. For current measurements up to 200mA DC/AC, set the function switch to the μ A/mA position
- Press the MODE button to indicate "DC" / "AC" on the display.
- 4. Remove power from the circuit under test, then open up the circuit at the point where you wish to measure current.
- Connect the black test probe tip to the negative side of the circuit.
 Connect the red test probe tip to the positive side of the circuit.
- 6. Apply power to the circuit.
- 7. Read the current in the display

NOTE: 0.2A/500V fast acting Resettable Fuse current inputs and Overload protection on mA, μA ranges. No replacement required.

RESISTANCE MEASUREMENT

- MARNING: To avoid electric shock, disconnect power to the unit under test and discharge all capacitors before taking any resistance measurements. Remove the batteries and unplug the line cords.
- 1. Set the function switch to the H 🗘 position.
- Press the MODE button to indicate Ω on the display.
- Touch the test probe tips across the circuit or part under test. It is best to disconnect one side of the part under test so the rest of the circuit will not interfere with the resistance reading.
- 4. Read the resistance in the display

CONTINUITY CHECK

MARNING: To avoid electric shock, never measure continuity on circuits or wires that have voltage on them.

- Set the function switch to the → →Ω position.
- Press the MODE button to indicate
 on the display
- 3. Connect the test probe tips to the circuit or wire you wish to check.
- If the resistance is less than approximately 150Ω, the audible signal will sound. If the circuit is open, the display will indicate "OL".

DIODE TEST

- Set the function switch to the + Ω position.
- Press the MODE button to indicate + on the display.
- Connect the test probes to the diode under test. Forward voltage will typically indicate 0.400 to 0.700V. Reverse voltage will indicate "OL". Shorted devices will indicate near OV and an open device will indicate "OL" in both polarities

NON-CONTACT AC VOLTAGE MEASUREMENTS

MARNING: Risk of Electrocution. Before use, always test the Voltage Detector on a known live circuit to verify proper operation

- Connect the probe tip to the hot conductor or insert into the hot side of the electrical outlet.
- 2. If AC voltage is present, the detector light will illuminate.

NOTE: The conductors in electrical cord sets are often twisted. For best results, rub the probe tip along a length of the cord to assure placing the tip in close proximity to the live conductor.

NOTE: The detector is designed with high sensitivity. Static electricity or other sources of energy may randomly trip the sensor. This is normal operation

HOLD BUTTON

The Data Hold function allows the meter to "freeze" a measurement for later reference

- Press the DATA HOLD button to "freeze" the display, the "HOLD" indicator will appear.
- 2. Press the **DATA HOLD** button to return to normal operation.

TORCH

Press and hold the top button to turn the torch on. Release the button to turn the torch off.

AUTO POWER OFF

The auto off feature will turn the meter off after 15 minutes.

REPLACING THE BATTERY

- Remove the bottom cover and secure the screw.
- Replace old battery with fresh Two 1.5V AAA type battery.
- Replace the bottom cover and secure the screw.